

VEHICLE INSPECTION REPORT

LY19GJO

Iveco Daily 35-140

Inspection

Serious Damage? No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	38817
Cap Code	IVDA233SRVHDTM2 4 L

Details

Location	Bedford	GVW	3500kg	CAP Clean	£4,575.00
Reg. date	01/03/2019	Colour	WHITE	CAP Average	£3,975.00
Year	2019	VIN	ZCFCC35A305267460	CAP Below	£3,075.00
Mileage	90,495 Miles Not Warranted	Body Style	Panel Van LWB	Gearbox	AUTOMATIC
Fuel Type	DIESEL	MOT Due	Expired	Gears	6

WARNING LIGHT ON DASH 3520 WB, TOW BAR, SINGLE SIDE LOAD DOOR, NEW KEEPER SLIP IN OFFICE

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Rear parking sensor
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



2: Bonnet
Chipped
Multiple Chips



3: Screen Front
Chipped
Over 10mm



4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



6: Door Moulding nsr
Scuffed (Unpainted)
Over 100mm



7: Lamp nsr
Broken
Replace

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Parking Brake		OK	Gearbox Static Gear Selection (engine running)		OK
			No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		Fault