COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

CX19DDN

Citroen Berlingo 650 1.6 BlueHDi Enterprise 75ps

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Id	43736
Cap Code	CIBE166E71VDTM2 4 L

Details

Location	Doncaster	**GVW**	2000kg	**CAP Clean**	£3,050.00
Reg. date	31/07/2019	**Colour**	WHITE	**CAP Average**	£2,625.00
Year	2019	**VIN**	VR7EFBHWBKJ685836	**CAP Below**	£2,050.00
Mileage	120,909 Miles Warranted	**Body Style**	Panel Van SWB	**Gearbox**	MANUAL
		MOT Due	30/07/2027	**Gears**	5
Fuel Type	DIESEL				

WARNING LIGHTS ON DASH DPF AND AD-BLUE ISSUES, AD -BLUE

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	


Features


- Bluetooth connection
- Air conditioning
- Cloth seat trim
- Cruise control
- Front electric windows
- Auxiliary input socket
- Drivers airbag
- Digital radio
- Central locking

Photos








CITROËN
0
mph
447 MI
120909 MI
SET 000



PSA Automobiles SA
e2*2007/46*0625
VR7EFBHWBKJ665836
2000 KG
3000 KG
1 – 1110 KG
2 – 1075 KG
EFBHWB – H2A021











KOOK

Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Panel Front
Chipped
Multiple Chips



3: Panel Front
Scratched
Over 25mm Thru Paint



4: Wing nsf
Dented
With Paint Damage



5: Door osr
Dented
With Paint Damage



6: Qtr Panel osr
Dented
With Paint Damage



7: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



8: Door osf
Scratched
Over 25mm Not Thru Paint



9: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault