

VEHICLE INSPECTION REPORT

WT69SYJ

Mercedes-Benz Actros 2545

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 31/10/2019

Year 2019

Mileage 373,368 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN WDB96342320406536

Body Style Tractor Unit

MOT Due 31/07/2026

Cab Type BIGSPACE CAB

Gearbox AUTOMATIC

Axle Combi 6x2

LOCATED NEAR SWINDON *COLLECTION STRICTLY BY PRIOR ARRANGEMENT* MIRROR CAMS, DIGITAL DASH, AD BLUE, SURROUND CAMERA SYSTEM

Tyres






NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Navigation system
- Park assist camera
- Air conditioning

Photos





Condition Check



Damage Photos



1: Wing nsf
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK