

VEHICLE INSPECTION REPORT

MF70AMO

Citroen Relay 35 2.2 BLUE HDI 140PS

Non Runner

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	29/10/2020	Colour	BLACK	CAP Average	£8,000.00
Year	2020	VIN	VF7YCBNFC12P95841	CAP Below	£6,425.00
Mileage	Not Showing	Body Style	Panel Van L3	Gearbox	MANUAL
Fuel Type	Diesel	CAP Clean	£9,100.00	Gears	6

NON-RUNNER, ENGINE STRIPPED MOT SHOWS 40,161 MILES 10/11/2023, JETTING REEL IN REAR, SIDE LOADING DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Rear parking sensor
- Front electric windows

Photos





Condition Check



Damage Photos



1: Other
N/A
N/A

2: Other
N/A
N/A



3: Bonnet
Chipped
Multiple Chips

4: Screen Front
Cracked
Replace



5: Other
N/A
N/A

6: Door Mirror Assy nsf
Broken
Replace



7: Handle Outer nsr
Broken
Replace

8: Sill ns
Dented
Over 30mm



9: Other
N/A
N/A

10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



11: Qtr Panel Trim ns
Scuffed
Over 25mm

12: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



13: Qtr Panel osr
Dented
With Paint Damage

14: Door Window osf
Missing
Replace



15: Door Mirror Assy osf
Broken
Replace

16: Door Mirror Glass os
Missing
Replace



17: Other
N/A
N/A

18: Other
N/A
N/A



19: Other
N/A
N/A

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	No
Engine Runs	Fault		