

VEHICLE INSPECTION REPORT

YB67WOM

MERCEDES-BENZ ACTROS 2551

Inspection

Vehicle

VAT	Plus VAT
V5	Present

Details

Reg. date	19/01/2018	VIN	WDB96342320228479	Axle Combi	6x2
Year	2018	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Mileage	823,059 Km Not Warranted	MOT Due	28/02/2026	Rear Suspension	Air
Fuel Type	Diesel	Cab Type	GIGASPACE CAB		
Colour	WHITE	Gearbox	AUTOMATIC		

SLIDING 5TH WHEEL

Tyres

NSF
NSR
OSF
OSR
Spare

Features

- Park assist camera
- Digital radio
- Air conditioning

Photos





